

REMARKS

An error has been discovered in the text of the above-identified application, and this error has been corrected above.

Reference numeral 36 relates to a driving circuit (page 55, lines 4 and 5, and line 18). It is element 32 which relates to a voltage-elevating circuit (page 55, line 3); also see Fig. 3. Accordingly, no new matter is introduced by the correction made above.

Respectfully submitted,

BROWDY AND NEIMARK, P.L.L.C.
Attorneys for Applicant

By



Sheridan Neimark
Registration No. 20,520

SN:jec
Telephone No.: (202) 628-5197
Facsimile No.: (202) 737-3528
G:\BN\S\SUMA\Fujiwara4\Pto\2006-10-11 PREL AMD.doc